



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Cole Nichols (colen@horizonenvservices.com)
Submission Date:	Mar 4, 2020 8:17:12 AM MST
Server Receive Date:	Mar 4, 2020 8:20:06 AM MST
Reference Number:	20200304-18135366592
Location:	557 Airpark Dr, Durango, CO 81303, USA Mar 4, 2020 8:19:25 AM MST [View Map]

Information

Name	colen@horizonenvservices.com
Date	Mar 3, 2020
Well Name	SHORT, LYLE GAS UNIT A 1
API Number	50670691100
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Clean Up Weed Debris

Photo of first corrective action completed



Completed work description Corrective Action 1

location sign

Photo of second corrective action completed



Completed work description of corrective action 2

before mowing

Photo of third corrective action completed



Completed work description of corrective action 3
 Photo of fourth corrective action completed

before mowing



Completed work description
 Completed work description of corrective action 4
 Additional photos

before mowing
 mowed and removed weed debris from fenceline



Additional photos



Additional photos



Additional photos



Completed work description
Summary of all work completed

mowed and removed weed debris from location
initial treatment 6/14/19