

**Location Name: – Central Operating Inc. – CO State Tank Battery – Spill ID 454308, Rem #3744**  
**Inspection Date: 03/02/2020**



**Photo # 1 – View southeast from south side of tank battery location toward State 1 well (121-08118)**

**Location Name: – Central Operating Inc. – CO State Tank Battery – Spill ID 454308, Rem #3744**  
**Inspection Date: 03/02/2020**



**Photo # 2 – View southeast from south side of tank battery location toward State 1 well (121-08118)**



**Location Name: – Central Operating Inc. – CO State Tank Battery – Spill ID 454308, Rem #3744**  
**Inspection Date: 03/02/2020**



**Photo # 3 – View east from west side of historic spill/land treatment area associated with Rem #3744. Note lack of vegetation**

**Location Name: – Central Operating Inc. – CO State Tank Battery – Spill ID 454308, Rem #3744**  
**Inspection Date: 03/02/2020**



**Photo # 4 – View north from west side of historic spill/land treatment area associated with Rem #3744. Note lack of vegetation**



**Location Name: – Central Operating Inc. – CO State Tank Battery – Spill ID 454308, Rem #3744**  
**Inspection Date: 03/02/2020**



**Photo # 5 – View south from west side of historic spill/land treatment area associated with Rem #3744. Note lack of vegetation**

**Location Name: – Central Operating Inc. – CO State Tank Battery – Spill ID 454308, Rem #3744**  
**Inspection Date: 03/02/2020**



**Photo # 6 – View west from area of historic spill/land treatment area associated with Rem #3744. Note lack of vegetation**



Location Name: – Central Operating Inc. – CO State Tank Battery – Spill ID 454308, Rem #3744  
Inspection Date: 03/02/2020



**Photo # 7 – Closeup view of area of historic spill/land treatment area associated with Rem #3744. Note lack of vegetation. Note clumps of hard, oily sand not found outside non-vegetated area.**

Location Name: – Central Operating Inc. – CO State Tank Battery – Spill ID 454308, Rem #3744  
Inspection Date: 03/02/2020



**Photo # 8 – Closeup view of area of historic spill/land treatment area associated with Rem #3744. Note lack of vegetation. Note clumps of hard, oily sand not found outside non-vegetated area.**



Location Name: – Central Operating Inc. – CO State Tank Battery – Spill ID 454308, Rem #3744  
Inspection Date: 03/02/2020



Photo # 9 – Closeup view of area of historic spill/land treatment area associated with Rem #3744. Note lack of vegetation. Note clumps of hard, oily sand not found outside non-vegetated area.