

Inspection Photos
Location Name: ALABASTER 11-8 FOLLOWUP
API#: 05-071-08642
INSP. #: 695102283



Colorado Oil & Gas Conservation Commission
37.02566, -104.49617, 86°
2020/03/05 09:54:26



Colorado Oil & Gas Conservation Commission
37.18937 -104.81135, 2170.0m, 100°
2020/03/05 09:56:30

PHOTO 1: LOCATION

PHOTO 2: WELL SIGN/ UNUSED EQUIPMENT STORED ON LOCATION (THERE ARE SEVERAL PIECES OF PIP FITTING & HOSED ETCL AROUND LOCATION). **COMPLY WITH GENERAL HOUSE KEEPING RULES 603.f. CA DATE 4-5-20.**

Inspection Photos
Location Name: ALABASTER 11-8 FOLLOWUP
API#: 05-071-08642
INSP. #: 695102283



PHOTO 3: GAS METER CAL. REPORT



PHOTO 4: UNUSED EQUIPMENT STORED ON LOCATION (THERE ARE SEVERAL PIECES OF PIP FITTING & HOSED ETCL AROUND LOCATION). **COMPLY WITH GENERAL HOUSE KEEPING RULES 603.f. CA DATE 4-5-20.**

Inspection Photos

Location Name: ALABASTER 11-8 FOLLOWUP

API#: 05-071-08642

INSP. #: 695102283



PHOTO 5: UNUSED EQUIPMENT STORED ON LOCATION (THERE ARE SEVERAL PIECES OF PIP FITTING & HOSED ETCL AROUND LOCATION). COMPLY WITH GENERAL HOUSE KEEPING RULES 603.f. CA DATE 4-5-20.

PHOTO 6: UNUSED EQUIPMENT STORED ON LOCATION (THERE ARE SEVERAL PIECES OF PIP FITTING & HOSED ETCL AROUND LOCATION). COMPLY WITH GENERAL HOUSE KEEPING RULES 603.f. CA DATE 4-5-20.

Inspection Photos

Location Name: ALABASTER 11-8 FOLLOWUP CA DATE 4-5-20

API#: 05-071-08642

INSP. #: 695102283



PHOTO 7: IMPACTED SOIL/GRAVEL NEAR PRIME MOVER ENGINE SKID. Conduct maintenance on equipment (ie REPAIR LEAKS ON ALL EQUIPMENT), cleanup stained material and review self inspection processes. CA DATE 4-5-20

PHOTO 8: IMPACTED SOIL/GRAVEL NEAR PRIME MOVER ENGINE SKID. Conduct maintenance on equipment (ie REPAIR LEAKS ON ALL EQUIPMENT), cleanup stained material and review self inspection processes. CA DATE 4-5-20

Inspection Photos

Location Name: ALABASTER 11-8 FOLLOWUP CA DATE 4-5-20

API#: 05-071-08642

INSP. #: 695102283



PHOTO 9: APEARS TO BE ENGINE OIL IN PRIME MOVER ENGINE SKID. **Comply with general provisions of the oil and gas act for wildlife protection. CA DATE 4-5-19.**

PHOTO 10: OILY WATER IN COMPRESSOR SKID. **Comply with general provisions of the oil and gas act for wildlife protection. CA DATE 4-5-19.**