

**Inspection Photos**  
**Location Name: State Antelope B-33 PAD**  
**Location ID: 432287**




**Photo 1 – Tank Battery**




**Photo 2 – Wells**



**Inspection Photos**  
**Location Name: State Antelope B-33 PAD**  
**Location ID: 432287**



**Photo 3 – Well 11-41-33HNB missing Wellhead Signage**



**Photo 4 – Unmarked Riser**



**Inspection Photos**  
**Location Name: State Antelope B-33 PAD**  
**Location ID: 432287**



**Photo 5 – Unmarked Riser**



**Photo 6 – Unmarked Riser**



**Inspection Photos**  
**Location Name: State Antelope B-33 PAD**  
**Location ID: 432287**




**Photo 7 – Unmarked Risers**



**Photo 8 – Unmarked Riser**



**Inspection Photos**  
**Location Name: State Antelope B-33 PAD**  
**Location ID: 432287**



**Photo 9 – Unmarked Risers**



**Photo 10 – Unmarked Riser**