


**Inspection Photos**  
**Location Name: State Antelope P-32 PAD**  
**Location ID: 432677**



**Photo 1 – Wells**




**Photo 2 – Unmarked Riser south of Pumping Unit**



**Inspection Photos**  
**Location Name: State Antelope P-32 PAD**  
**Location ID: 432677**




**Photo 3 – Stained Soil at P-T-32 Well**



**Photo 4 – Stained Soil at P41-T44-32HNC Well**

**Inspection Photos**  
**Location Name: State Antelope P-32 PAD**  
**Location ID: 432677**



**Photo 5 – Stained Soil at 41-44-32HNB Well**