

Inspection Photos
Location Name: State Antelope F-32 PAD
Location ID: 432686



Photo 1 – Tank Battery




Photo 2 – Wells



Inspection Photos
Location Name: State Antelope F-32 PAD
Location ID: 432686




Photo 3 – Unmarked Risers at Separators




Photo 4 – Unmarked Riser at Separators



Inspection Photos
Location Name: State Antelope F-32 PAD
Location ID: 432686




Photo 5 – Stained Soil at Separators




Photo 6 – Stained Soil at drain valve



Inspection Photos
Location Name: State Antelope F-32 PAD
Location ID: 432686



Photo 7— Stained Soil at drain valve




Photo 8 – Stained Soil and Unmarked Risers at Compressor

