

Inspection Photos
Operator: BP America
API#: 067-06340
Date: 3/10/2020



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of young musk thistle rosettes observed within the interim reclamation area. Approximately 100 individuals observed.



Photo 3. View of musk thistles that appear to be treated with herbicide.



Photo 4. View of dense Russian thistle debris within the southern project area.



Photo 5. View of unconsolidated berm and bare soils within the southwestern project area, needing stabilization.



Photo 6. View of reference area vegetation comprised of sagebrush shrubland with grassy understory, dominated by sand dropseed and James galleta.