

Inspection Photos

API: 071-07011

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 3/12/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07011 | Date: 3/12/2020

Inspection Photos



Photo 1. The culvert outlet has filled in with sediment at Lat/Long:37.05764,-104.81458.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07011 | Date: 3/12/2020

Inspection Photos



Photo 2. There is a culvert inlet at this area that is filled in with sediment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07011 | Date: 3/12/2020

Inspection Photos



Photo 3. Facing southwest toward the location.

