

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/12/2020

Submitted Date:

03/13/2020

Document Number:

688307269**FIELD INSPECTION FORM**Loc ID 322170 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 74165Name of Operator: RENEGADE OIL & GAS COMPANY LLCAddress: 6155 S MAIN STREET #225City: AURORA State: CO Zip: 80016**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|----------------|----------------|--------------------------|---------------------------------|
| Condill, JB | 303-680-4725 | jbcrog@aol.com | All Inspections |
| Ingve, Ed | 303-829-2354 | ed@renegadeoilandgas.com | All Inspections |
| Espinosa, Bill | (303) 829-4982 | billespinosa30@yahoo.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 209471 | WELL | PR | 02/03/2004 | GW | 039-06376 | MILLER 6-15 | PR |

General Comment:[Routine Inspection](#)

Form 4 VENT_FLARE is in process: 402178324 04 -00 -VENT_FLARE IN PROCESS 09/16/2019 RENEGADE OIL & GAS COMPANY LLC.

LocationOverall Good: ☒**Signs/Marker:**

| | | | |
|--------------------|----------|-------|--|
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment: 303-680-4725

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

| | | | |
|--------------------------|-----|-------|-----------------|
| Type: Deadman # & Marked | # 4 | | corrective date |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Pump Jack | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Prime Mover | # 1 | | |
| Comment: gas engine | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| | | | | | |
|--------------------|---|----------|---------------------|---------|--------|
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| | | | CENTRALIZED BATTERY | | , |
| Comment: | | | | | |
| Corrective Action: | | Date: | | | |

Paint

| | |
|------------------|--|
| Condition | |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| | | | | |
|----------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| | | | | |
| Comment: | | | | |

| | | | |
|--------------------|--|-------|--|
| Corrective Action: | | Date: | |
|--------------------|--|-------|--|

Venting:

| | | | |
|--------------------|--|-------|--|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| | | | |
|--|--|--|--|
| | | | |
|--|--|--|--|

Inspected FacilitiesFacility ID: 209471 Type: WELL API Number: 039-06376 Status: PR Insp. Status: PR**Producing Well**Comment: [PR. Dec 2019 production reported to COGCC database.](#)

Corrective Action:

Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 688307295 | Renegade Miller 6-15 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5096222 |