

Final Reclamation Inspection

March 5, 2020

Operator: FOUNDATION ENERGY MANAGEMENT LLC- #10112

Location ID: 453784

Inspection Document #: 697501218

Weld County, CO

NESE Section 7 T7N R59W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Andrews Tank Battery
Location ID: 453784



Photo 1. Photo taken from the southern tank battery location, facing North. Photo illustrates Operator has failed to remove equipment and debris from location and conduct reclamation of the location.

Inspection Photos
Location Name: Andrews Tank Battery
Location ID: 453784




Photo 2. Photo taken from the pit, facing West. Photo illustrates Operator has backfilled the pit area (area inside the red-dashed line). The pit area consists mostly of weedy, annual vegetation which is not reflective of reference area vegetation.

Inspection Photos
Location Name: Andrews Tank Battery
Location ID: 453784



Photo 3. Photo taken from the tank battery location, facing Northeast. Photo illustrates Operator has failed to remove equipment and conduct reclamation of the location.



Photo 4. Photo taken from the tank battery location, facing East. See comments under Photo 3.

Inspection Photos
Location Name: Andrews Tank Battery
Location ID: 453784



Photo 5. Photo taken from the tank battery location, facing East. See comments under Photo 3.



Photo 6. Photo taken from the tank battery location, facing North. See comments under Photo 3.

Inspection Photos
Location Name: Andrews Tank Battery
Location ID: 453784



Photo 7. Photo taken from the tank battery location, facing East. Photo illustrates Operator has failed to clean up and remediate contaminated soils from a leaky tank.



Photo 8. Photo taken from the tank battery location. See comments under Photo 7.