

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/16/2020

Submitted Date:

03/16/2020

Document Number:

700700284

FIELD INSPECTION FORM

Loc ID 334791 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Findings:

8 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|---------------------------------------|---------|
| , Caerus | | COGCC.inspections@caerusoilandgas.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------------------|-------------|
| 89036 | WELL | PR | 10/01/2003 | GW | 045-07364 | COUEY 17-11 | PR |
| 256088 | WELL | PR | 12/07/1999 | GW | 045-07421 | COUEY 17-10 | PR |
| 276747 | WELL | SI | 11/01/2019 | GW | 045-10519 | COUEY 17-11D(K17E) | SI |
| 276749 | WELL | PR | 12/01/2019 | GW | 045-10520 | COUEY 17-15B (K17E) | PR |
| 276871 | WELL | PR | 10/01/2017 | GW | 045-10546 | COUEY FEDERAL 17-14A (K17E) | PR |

General Comment:

COGCC Inspection Report Summary
On Monday 3/16/20 at approximately 10:00 AM, I, Inspector Scott Ramsey, conducted a follow up inspection at Caerus K17E, at Location # 334791 in Garfield Colorado.
While there, I observed normal production operations. All C/A(s) have been completed from previous inspection document # 694900688
This is a summary of inspection report.

Location

| | | | |
|--------------------|--------|--|-------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | | | |
| Corrective Action: | | | Date: |

Overall Good:

| | | | |
|----------------------|----------------------|--|-------|
| Signs/Marker: | | | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type | CONTAINERS | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

| | | | |
|---------------------------|-----|--|-------------|
| Emergency Contact Number: | | | |
| Comment: | 911 | | |
| Corrective Action: | | | Date: _____ |

| | | | |
|---------------------------|--------|--|-------|
| Good Housekeeping: | | | |
| Type | DEBRIS | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Overall Good:

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

Multiple Spills and Releases?

| | | | |
|--------------------|-----------|--|-------|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type | SEPARATOR | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

| Equipment: | | corrective date |
|-----------------------------------|----------------|-----------------|
| Type: Gas Meter Run | # 1 | |
| Comment: | | |
| Corrective Action: | | Date: |
| Type: Horizontal Heated Separator | # 2 | |
| Comment: | | |
| Corrective Action: | | Date: |
| Type: Vertical Heated Separator | # 3 | |
| Comment: | | |
| Corrective Action: | | Date: |
| Type: Ancillary equipment | # 3 | |
| Comment: | chemical tanks | |
| Corrective Action: | | Date: |
| Type: Plunger Lift | # 5 | |
| Comment: | | |
| Corrective Action: | | Date: |
| Type: Bird Protectors | # 3 | |
| Comment: | | |
| Corrective Action: | | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CONDENSATE | 2 | 300 BBLs | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | |
|--------------------|----|-------|
| Yes/No | NO | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | |
|------|--|
| Type | |
|------|--|

| | | |
|--------------------|--|-------|
| Comment: | | |
| Corrective Action: | | Date: |

| | | |
|--|--|--|
| | | |
|--|--|--|

| Inspected Facilities | | | | |
|--|--|------------------------------|-------------------|-------------------------|
| Facility ID: <u>89036</u> | Type: <u>WELL</u> | API Number: <u>045-07364</u> | Status: <u>PR</u> | Insp. Status: <u>PR</u> |
| Producing Well | | | | |
| Comment: <u>producing</u> | | | | |
| Corrective Action: | | | Date: | |
| Facility ID: <u>256088</u> | Type: <u>WELL</u> | API Number: <u>045-07421</u> | Status: <u>PR</u> | Insp. Status: <u>PR</u> |
| Producing Well | | | | |
| Comment: <u>producing</u> | | | | |
| Corrective Action: | | | Date: | |
| Facility ID: <u>276747</u> | Type: <u>WELL</u> | API Number: <u>045-10519</u> | Status: <u>SI</u> | Insp. Status: <u>SI</u> |
| Idle Well | | | | |
| Purpose: <input checked="" type="checkbox"/> Shut In | <input type="checkbox"/> Temporarily Abandoned | Reminder: _____ | | |
| Comment: <u>shut in</u> | | | | |
| Corrective Action: | | | Date: | |
| Facility ID: <u>276749</u> | Type: <u>WELL</u> | API Number: <u>045-10520</u> | Status: <u>PR</u> | Insp. Status: <u>PR</u> |
| Producing Well | | | | |
| Comment: <u>producing</u> | | | | |
| Corrective Action: | | | Date: | |
| Facility ID: <u>276871</u> | Type: <u>WELL</u> | API Number: <u>045-10546</u> | Status: <u>PR</u> | Insp. Status: <u>PR</u> |
| Producing Well | | | | |
| Comment: <u>producing</u> | | | | |
| Corrective Action: | | | Date: | |

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Berms | | Culverts | | | | |
| Ditches | | Gravel | | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-----------------|---|
| 700700288 | photos for K17E | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5097595 |