

Inspection Photos

Loc#323894

Operator: Terra

Inspection Number: 692402001

Inspection Date: 3/12/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:

View of Location from entry to East.

March 12,, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra RMV Loc#323894



Photo#2:
Marker needing bright color.



Photo#3:
Marker needing bright color.

March 12,, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra RMV Loc#323894



Photo#4:
Interim area.



Photo#5:
Cut Slope.

March 12,, 2020