

# *Inspection Photos*

*Loc#324113*

*Operator: Terra*

*Inspection Number: 692402003*

*Inspection Date: 3/12/20*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:

View of Location from entry to East and Anchor Marker needing bright color.

March 12,, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra Burns Loc#324113





Photo#2:  
Hole developing in containment.



Photo#3:  
Hole developing in containment.

March 12,, 2020





Photo#4:  
Weedy Interim area.



Photo#5:  
Weedy Interim area.

March 12,, 2020