


RGU 42-27-198 pad  
API: 05-103-12087 to 12104, 12144  
Inspection: 700400502



39.93956, -108.36808, 6547.7ft, 299°  
03/16/2020 11:20:39 AM



RGU 42-27-198 pad  
API: 05-103-12087 to 12104, 12144  
Inspection: 700400502



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 2. Separator risers.**



RGU 42-27-198 pad  
API: 05-103-12087 to 12104, 12144  
Inspection: 700400502



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 3. Tanks.**

RGU 42-27-198 pad  
API: 05-103-12087 to 12104, 12144  
Inspection: 700400502



39.9396, -108.36814, 6547.0ft, 336°  
03/16/2020 11:20:54 AM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 4. Pit.**



RGU 42-27-198 pad  
API: 05-103-12087 to 12104, 12144  
Inspection: 700400502



39.94076, -108.36917, 6531.9ft, 64°  
03/16/2020 11:14:17 AM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 5. Pit.**



RGU 42-27-198 pad  
API: 05-103-12087 to 12104, 12144  
Inspection: 700400502



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 6. Location trash.**