

240 pad
Inspection: 700400508



240 pad
Inspection: 700400508



39.85614, -108.33894, 6234.7ft, 211°
03/16/2020 12:32:15 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Tanks.

240 pad
Inspection: 700400508



240 pad
Inspection: 700400508



39.85614, -108.3394, 6240.8ft, 254°
03/16/2020 12:32:53 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 4. Emission control devices.

240 pad
Inspection: 700400508



39.85596, -108.33785, 6232.8ft, 76°
03/16/2020 12:23:35 PM

240 pad
Inspection: 700400508




COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 6. Well heads.

240 pad
Inspection: 700400508



240 pad
Inspection: 700400508



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 8. Well 103-11217. Well status of "XX" or not drilled. The well name doesn't agree with API number.

240 pad
Inspection: 700400508



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 9. Well 103-12388. Well status of "DG" or drilling.

240 pad
Inspection: 700400508



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 10. Well 103-12341 of "DG" or drilling.

240 pad
Inspection: 700400508



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 11. Well 103-12335 of "PR" or producing. The well name doesn't agree with API number.