

27A pad  
API: 05-103-11020, 11021  
Inspection: 700400510



39.85181, -108.3726, 6345.6ft, 236°  
03/16/2020 12:44:47 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 1. Location.**



27A pad  
API: 05-103-11020, 11021  
Inspection: 700400510



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 2. Well heads.**



27A pad  
API: 05-103-11020, 11021  
Inspection: 700400510



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 3. Separator.**



27A pad  
API: 05-103-11020, 11021  
Inspection: 700400510



39.85148, -108.37346, 6362.5ft, 306°  
03/16/2020 12:47:14 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 4. Tanks.**

27A pad  
API: 05-103-11020, 11021  
Inspection: 700400510



39.85162, -108.37364, 6352.1ft, 9°  
03/16/2020 12:48:04 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 5. Liner hole.**