

# Final Reclamation Inspection

March 5, 2020

Operator: FOUNDATION ENERGY MANAGEMENT LLC- #10112

Location ID: 327445

Inspection Document #: 697501239

Weld County, CO

NESW Section 7 T7N R59W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources



**Photo 1.** Photo taken from the western well location access road, facing East. Photo illustrates the access road has not been properly contoured to match the surrounding landscape. Refer to Photo #2 regarding contouring.

Also, it is unclear whether the access road/well location has been properly cross-ripped and whether it was seeded. Currently, there is no establishment of crop species observed throughout the access road and well location. Staff will have to make a future assessment during the active growing season to make a better assessment.

Inspection Photos  
Location Name: ROTH #11-7R  
Location ID: 327445



**Photo 2.** Photo taken from the central well location access road, facing West. Photo illustrates the access road has not been properly contoured. The access road is in the shape of a “v”.



Inspection Photos  
Location Name: ROTH #11-7R  
Location ID: 327445



**Photo 3.** Photo taken from the central well location access road, facing East. See comments under Photo 1.

Inspection Photos  
Location Name: ROTH #11-7R  
Location ID: 327445



**Photo 4.** Photo taken from the eastern well location access road, facing East. Photo illustrates weedy, annual vegetation consisting of but not limited to: *Eragrostis cilianensis* (stinkgrass), *Kochia* and Russian thistle.




Inspection Photos  
Location Name: ROTH #11-7R  
Location ID: 327445



**Photo 5.** Photo taken from the western well location, facing East. See comments under Photo 1 and 4.

Inspection Photos  
Location Name: ROTH #11-7R  
Location ID: 327445



**Photo 6.** Photo taken from the northern well location, facing East. See comments under Photo 1 and 4.