

Final Reclamation Inspection

March 5, 2020

Operator: FOUNDATION ENERGY MANAGEMENT LLC- #10112

Location ID: 327573

Inspection Document #: 697501241

Weld County, CO

SESE Section 7 T7N R59W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: ANDREWS #16-7
Location ID: 327573



Photo 1. Photo taken from the southern well location access road, facing North. Photo illustrates the establishment of crops within the access road that appears reflective of reference crop areas.

Inspection Photos
Location Name: ANDREWS #16-7
Location ID: 327573



Photo 2. Photo taken from the southern well location, facing Northwest. Photo illustrates crop rows circling the well location indicating the well location was not seeded.

Inspection Photos
Location Name: ANDREWS #16-7
Location ID: 327573




Photo 3. Photo taken from the southern well location, facing Northeast. See comments under Photo 2.

Inspection Photos
Location Name: ANDREWS #16-7
Location ID: 327573



Photo 4. Photo taken from the northern well location, facing East. See comments under Photo 2.

Inspection Photos
Location Name: ANDREWS #16-7
Location ID: 327573




Photo 5. Photo taken from the western well location, facing South. See comments under Photo 2.