

# Inspection Photos

3/17/2020

Operator: RIO MESA RESOURCES INC - 74740

Location ID: 314813

Rio Blanco County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: RIO MESA RESOURCES INC - 74740  
Location ID: 314813



**Photo 1:** Photo taken from the well, facing south. Photo shows pumping unit and signage.



**Photo 2:** Continued from photo 1. Photo shows signage at well, including emergency contact; Inspector was unable to immediately contact Operator via the emergency contact number.



Inspection Photos  
Operator Name: RIO MESA RESOURCES INC - 74740  
Location ID: 314813



**Photo 3:** Photo taken from the battery, on the east end of the Location, facing east. Photo shows signage at battery, including two emergency contact numbers; Inspector was unable to immediately contact Operator via either the emergency contact number.



**Photo 4:** Photo taken from the wellhead, facing south. Photo shows stained soils around the well. 6 foot measuring stick for reference.



Inspection Photos  
Operator Name: RIO MESA RESOURCES INC - 74740  
Location ID: 314813



**Photo 5:** Photo taken from the wellhead, facing east. Photo shows stained soils around the well. 6 foot measuring stick for reference.



**Photo 6:** Photo taken at the well head. Photo shows containment cellar; various chemicals/fluids appear to have discharged into the containment BMP; chemicals/fluids require removal. Photo also shows various chemicals/fluids on the well/casing



Inspection Photos  
Operator Name: RIO MESA RESOURCES INC - 74740  
Location ID: 314813



**Photo 7:** See comments under photo 6.



**Photo 8:** Photo taken from the well head. It was observed that gas appears to be venting from equipment attached to the bradenhead. Arrow shows open valve where gas appear to be venting from.



Inspection Photos  
Operator Name: RIO MESA RESOURCES INC - 74740  
Location ID: 314813



**Photo 9:** See comments under photo 8.



**Photo 10:** Photo taken from the east end of the Location, facing west. Photo shows overview of the Location.



Inspection Photos  
Operator Name: RIO MESA RESOURCES INC - 74740  
Location ID: 314813



**Photo 11:** Photo taken from the east end of the Location, facing northwest. Photo provides overview of the Location.

