

Inspection Photos

3/17/2020

Operator: RIO MESA RESOURCES INC - 74740

Location ID: 397812

Rio Blanco County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: RIO MESA RESOURCES INC - 74740
Location ID: 397812



Photo 1: Photo taken from the south end of the Location, facing North. Photo shows well site.



Inspection Photos
Operator Name: RIO MESA RESOURCES INC - 74740
Location ID: 397812



Photo 2: Photo shows well casing; Well does not appear to have been sufficiently plugged or cut/capped or in compliance with Rule 319.a.(5).



Inspection Photos
Operator Name: RIO MESA RESOURCES INC - 74740
Location ID: 397812



Photo 3: Photo taken from the well location, facing east. See comments under photo 2.



Inspection Photos
Operator Name: RIO MESA RESOURCES INC - 74740
Location ID: 397812



Photo 4: Photo taken from the east end of the Location, facing northeast. Photo shows Oil and Gas associated utility equipment remains on the Location.

