

Inspection Photos

Location Name: VPR C NO. 84 CA DATE 4-18-20

API#: 05-071-07386

INSP. #: 695102301



PHOTO 1: LOCATION

PHOTO 2: WELL SIGN

Inspection Photos

Location Name: VPR C NO. 84 CA DATE 4-18-20

API#: 05-071-07386

INSP. #: 695102301



PHOTO 3: THERE IS AN AREA APP. 3' IN DIAMETER OF IMPACTED SOIL APPEARS TO BE COMING FROM POLISH ROD OILER. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. CA DATE 4-18-20.