

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/11/2020

Submitted Date:

03/12/2020

Document Number:

699700109**FIELD INSPECTION FORM**Loc ID 334868 Inspector Name: Heil, John On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Gardner, Mike		mgardner@terraep.com	
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	
Fischer, Alex		alex.fischer@state.co.us	

General Comment:

On March 11, 2020, COGCC Environmental Staff (John Heil) conducted an environmental field inspection of TEP ROCKY MOUNTAIN LLC (TEP operator #96850) Location ID 334868 GM 34-33 Spill ID 447506.

Environmental**Spills/Releases:**

Type of Spill: PRODUCED WATER

Estimated Spill Volume: _____

Comment: 8/26/2016 TEP submitted an eForm 19 Initial when a pin-hole leak on the bottom of a Produced Water steel AST caused fluids to be spilled/released into an earthen secondary containment (F19 Initial Doc #401100232). A COGCC inspection was conducted on 8/29/2016 to examine the spill/release area and remediation activities. The impacted material from the spill/release was landfarmed on location just north of where the spill occurred (Doc #674300756). There was no evidence of a landfarm or excavation on location during 3/11/2020 inspection, see photos.

Corrective Action: Operator shall provide the status and update of Spill/Release 447506 on a Supplemental F19.

Date: 04/26/2020

Reportable: YES

GPS: Lat _____ Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402341229	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5094417
699700110	20200312 Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5094404