



Form Information

Form Name: **Compliance Follow Up Form**
Submitter Name: Cole Nichols (colen@horizonenvservices.com)
Submission Date: Mar 9, 2020 4:58:15 PM MDT
Server Receive Date: Mar 9, 2020 5:01:09 PM MDT
Reference Number: 20200309-18135840749
Location: 557 Airpark Dr, Durango, CO 81303, USA
Mar 9, 2020 4:57:18 PM MDT [[View Map](#)]

Information

Name colen@horizonenvservices.com
Date Jan 24, 2020
Well Name MAYFIELD GAS UNIT A 1
Select State Colorado
Work type COGCC Inspection AR
Action Complete Clean Up Weed Debris

Photo of first corrective action completed



Completed work description Corrective Action 1

sign

Photo of second corrective action completed



Completed work description of corrective action 2

weed debris removed

Photo of third corrective action completed



Completed work description of corrective action 3
Completed work description
Completed work description of corrective action 4
Completed work description
Summary of all work completed

weed debris removed
na
na
weed debris removed
weed debris removed