

Final Reclamation and Stormwater Inspection

March 12, 2020

Operator: PDC ENERGY INC - 69175

Location ID: 320371

Inspection Document #: 697501243

Adams County, CO

NWNW Section 2 T1S R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: GUTHRIE #11-2
Location ID: 320371



Photo 1. Photo taken from the offsite tank battery (40.000100,-104.862450), facing East. Photo illustrates this tank battery is in use by other Operators (KPK and Petroshare).

Inspection Photos
Location Name: GUTHRIE #11-2
Location ID: 320371



Photo 2. Photo taken from the well location entrance, facing Northwest. Photo illustrates Operator failed to remove the culvert and gravel.

Inspection Photos
Location Name: GUTHRIE #11-2
Location ID: 320371



Photo 3. Photo taken from the well location entrance, facing Southwest. See comments under Photo 2.

Inspection Photos
Location Name: GUTHRIE #11-2
Location ID: 320371



Photo 4. Photo taken from the plugged and abandoned well, facing Southwest. Photo illustrates the well location has not been properly recontoured due to subsidence.