

**Inspection Photos**  
**Location Name: Oxbow 0880 S29**  
**Location ID: 458790**



**Photo 1. Overview of location taken facing west.**



**Photo 2. No label visible on tank.**