

Inspection Photos
Operator: Logos Operating
API#: 067-05180
Date: 3/16/2020



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the kochia debris at and around the wellhead.



Photo 3. View of unknown debris, approximately 15 feet long and 6 feet wide within the northwestern project area.



Photo 4. View of Russian knapweed within the western project area.



Photo 5. View of reference area vegetation, comprised of open pinyon-juniper woodland, with sagebrush and herbaceous understory.