

Inspection Photos

API: 071-06408

Operator: TIMBER CREEK OPERATING

Inspection Date: 3/19/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-06408 | Date: 3/19/2020

Inspection Photos



Photo 1. Facing south toward the location. Desirable vegetation has not established.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06408 | Date: 3/19/2020

Inspection Photos



Photo 2. Facing southwest at the location. There are areas that are bare of vegetation and the location needs to be reseeded.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06408 | Date: 3/19/2020

Inspection Photos



Photo 3. View of ground cover. There are some undesirable weeds (Kochia) and mostly bare ground.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06408 | Date: 3/19/2020

Inspection Photos



Photo 4. Facing northeast. Vehicle ruts are across the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06408 | Date: 3/19/2020