

Inspection Photos

API: 071-09239

Operator: TIMBER CREEK OPERATING

Inspection Date: 3/19/2020



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09239 | Date: 3/19/2020

Inspection Photos



Photo 1. Facing southwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09239 | Date: 3/19/2020

Inspection Photos



Photo 2. The electric fence around the pit is in disrepair and needs to be maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09239 | Date: 3/19/2020

Inspection Photos



Photo 3. There is oil on the engine skid and on soil that needs to be cleaned up.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09239 | Date: 3/19/2020