

Inspection Photos

API: 071-09279

Operator: TIMBER CREEK OPERATING

Inspection Date: 3/19/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09279 | Date: 3/19/2020

Inspection Photos



Photo 1. Facing northwest along the access road. Stormwater is flowing down and across the road shown in left photo. This is causing erosion of the road shown in right photo. This area needs to be repaired and stormwater needs to be properly diverted.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09279 | Date: 3/19/2020

Inspection Photos



Photo 2. The culvert along the access road is filled in with sediment. Arrow points to erosion shown in previous photo. Stormwater needs to be diverted to the culvert.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09279 | Date: 3/19/2020

Inspection Photos



Photo 3. There are multiple culverts filled in with sediment along the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09279 | Date: 3/19/2020

Inspection Photos



Photo 4. Facing back to the southwest along the access road. Stormwater is causing erosion down the road and is not properly diverted.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09279 | Date: 3/19/2020

Inspection Photos



Photo 5. Erosion is occurring along the side of the road near the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09279 | Date: 3/19/2020

Inspection Photos



Photo 6. Facing north toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09279 | Date: 3/19/2020

Inspection Photos



Photo 7. There is oil stained soil and oil on the engine skid that needs to be cleaned up.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09279 | Date: 3/19/2020

Inspection Photos



Photo 8. The oil on the engine skid on the other engine skid that needs to be cleaned up.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09279 | Date: 3/19/2020

Inspection Photos



Photo 9. The well sign is posted at the meter shed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09279 | Date: 3/19/2020