

Inspection Photos

Loc#383144

Operator: Terra

Inspection Number: 692402007

Inspection Date: 3/12/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:

View into Location from divergent access road.

March 12, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Youberg Loc#383144



Photo#2

Area of Cheat grass establishment.

March 12, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Youberg Loc#383144



Photo#3:
Weedy portion of site.




Photo#4:
Area with establishment of perennial Vegetation.

March 12, 2020



Photo#5:
Area repaired since previous Inspection



Photo#6:
Area repaired since previous Inspection.

March 12, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Youberg Loc#383144



Photo#7:
View up main Access road to NE (which may also be pipeline right of way).



Photo#8:
View down main Access Road to SW.

March 12, 2020



Photo#9:
Area of developing erosion concern.

March 12, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Youberg Loc#383144