

**Inspection Photos**  
**Location Name: Castor Federal LD14-68HN**  
**Location ID: 423037**



**Photo 1 – Tank Battery**



**Photo 2 – Signage**



**Inspection Photos**  
**Location Name: Castor Federal LD14-68HN**  
**Location ID: 423037**



**Photo 3 – Pumping Unit**



**Photo 4 – Produced Water Tank – Missing Content. NFPA and Capacity labels are fading/peeling off.**





**Inspection Photos**  
**Location Name: Castor Federal LD14-68HN**  
**Location ID: 423037**



**Photo 5 – Stained Soil at Exhaust**



**Photo 6 – Unused Containment and Stand**



**Inspection Photos**  
**Location Name: Castor Federal LD14-68HN**  
**Location ID: 423037**



Colorado Oil and Gas Conservation Commission  
40.75793, -103.83887, 4595.8ft, 348°  
03/17/2020 13:00:46

**Photo 7 – Unused Equipment at Header**