

Inspection Photos
Location Name: Castor Federal LD15-75HN
Location ID: 423364



Photo 1 – Tank Battery



Photo 2 – Dillos Fed Wellhead



Inspection Photos
Location Name: Castor Federal LD15-75HN
Location ID: 423364



Photo 3 – Castor Federal LD15 Wellheads



Photo 4 – Unused Chemical Tank at Castor Wellheads



Inspection Photos
Location Name: Castor Federal LD15-75HN
Location ID: 423364



Photo 5 – Tank Labels Fading/Peeling



Photo 6 – Unused Automation Equipment and Trash at Entrance