

# *Inspection Photos*

*Loc#322506*

*Operator: Grizzly*

*Inspection Number: 692402009*

*Inspection Date: 3/17/2020*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of location to North.

March 17,2020





Photo#2:  
Damaged /Unmarked Anchor



Photo#3:  
T Post Anchor

March 17,2020





Photo#4:  
Need for structured BMP.



Photo#5:  
Need for structured BMP.

March 17,2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Grizzly Friport Loc#322506





Photo#6:  
Culvert at lease road.



Photo#7:  
Culvert at lease road.


March 17, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Grizzly Friport Loc#322506





Photo#8:  
Sediment migration occurring.



Photo#9:  
Sediment migration occurring.

March 17, 2020