

# *Inspection Photos*

*Loc#335440*

*Operator: Grizzly*

*Inspection Number: 692402011*

*Inspection Date: 3/17/2020*



Photo#1:  
Overview of location to Southeast.

March 17,2020



Photo#2:

Any loose Piles of Soil are potential Pollution sources



Photo#3:

Any loose Piles of Soil are potential Pollution sources

March 17,2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Grizzly Stranahan Loc#335440





Photo#4:  
Need for structured BMP.



Photo#5:  
Need for structured BMP.

March 17, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Grizzly Stranahan Loc#335440



Photo#6:  
Sediment migration occurring.



Photo#7:  
Sediment migration occurring.

March 17,2020