



## Form Information

Form Name: **Compliance Follow Up Form**  
Submitter Name: Cole Nichols (colen@horizonenvservices.com)  
Submission Date: Mar 19, 2020 3:29:29 PM MDT  
Server Receive Date: Mar 19, 2020 3:32:29 PM MDT  
Reference Number: 20200319-18136992786  
Location: 557 Airpark Dr, Durango, CO 81303, USA  
Mar 19, 2020 3:28:37 PM MDT [ [View Map](#) ]

## Information

Name	colen@horizonenvservices.com
Date	Feb 7, 2020
Well Name	ZELLITTI GAS UNIT A 2
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Clean Up Land Owner Debris Clean Up Weed Debris Clean Up Contaminated Soils

Photo of first corrective action completed



Completed work description Corrective Action 1

debris removed

Photo of second corrective action completed



Completed work description of corrective action 2

stained soils removed


Photo of third corrective action completed



Completed work description of corrective action 3

debris removed

Photo of fourth corrective action completed



Completed work description

debris removed

Completed work description of corrective action 4

removed debris

Additional photos



Completed work description

cleaned up debris from around the well.

Summary of all work completed

cleaned up weed debris, soil stains and trash.