

**Inspection Photos**  
**Location Name: Flaherty 18 PAD**  
**Location ID: 443962**



**Photo 1 – Tank Battery**



**Photo 2 – Wells**

Inspection Photos  
Location Name: Flaherty 18 PAD  
Location ID: 443962



Photo 3 – Stained Soil at Wellhead

Photo 4 – Stained Soil at Wellhead

Inspection Photos  
Location Name: Flaherty 18 PAD  
Location ID: 443962



Photo 5 – Stained Soil at Wellhead, Unmarked Riser




Photo 6 – Unused Rods, Unmarked Riser

**Inspection Photos**  
**Location Name: Flaherty 18 PAD**  
**Location ID: 443962**



**Photo 7 – Unused Rods, Unmarked Riser**



**Photo 8 – Separators**

Inspection Photos  
Location Name: Flaherty 18 PAD  
Location ID: 443962



Colorado Oil and Gas Conservation Commission  
40 31063, -104 37528, 4490.8ft, 210°  
03/23/2020 11:36:59

Photo 9 – Stained Soil at North Separator



Colorado Oil and Gas Conservation Commission  
40 31073, -104 37573, 4490.8ft, 210°  
03/23/2020 11:37:28

Photo 10 – North 2 Separators are missing Wildlife screens.  
Unmarked 1" Risers

Inspection Photos  
Location Name: Flaherty 18 PAD  
Location ID: 443962




Photo 11 – Unmarked 1” Risers




Photo 12 – Unmarked 1” Risers

Inspection Photos  
Location Name: Flaherty 18 PAD  
Location ID: 443962




Photo 11 – Unmarked 1” Risers




Photo 12 – Unmarked 1” and 2” Risers

Inspection Photos  
Location Name: Flaherty 18 PAD  
Location ID: 443962



Photo 13 – Unmarked 1” Risers



Photo 14 – Unmarked 1” and 2” Risers


Inspection Photos  
Location Name: Flaherty 18 PAD  
Location ID: 443962



Photo 15 – Unmarked 1” Risers

Photo 16 – Weeds and Trash

**Inspection Photos**  
**Location Name: Flaherty 18 PAD**  
**Location ID: 443962**



**Photo 17 – Stained Soil and Unmarked Risers**