

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/25/2020

Submitted Date:

03/25/2020

Document Number:

701000338

FIELD INSPECTION FORM

Loc ID 303519 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10699
Name of Operator: OWN RESOURCES OPERATING LLC
Address: 38 PALMER CREST CT
City: SPRING State: TX Zip: 77381

Findings:

10 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Jones, Greg	(970) 630-3909	greg.jones@ownresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
253225	WELL	PR	03/11/1985	GW	125-07102	JONES 2	PR

General Comment:

[Routine Inspection](#)

Location

Lease Road:			
Type	Access		
comment:	Gravel road through pasture		
Corrective Action:			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign mounted to meter shed		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Labeling is faded and needs replaced		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Metal panels around wellhead, meter shed and water tank		
Corrective Action:			Date:

Equipment:					corrective date
Type: Vertical Separator	# 1				
Comment:	Vertical gas separator in metal shed				
Corrective Action:					Date:
Type: Gas Meter Run	# 1				
Comment:	Meter run in metal shed				
Corrective Action:					Date:
Type: Deadman # & Marked	# 4				
Comment:					
Corrective Action:					Date:

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	BV FIBERGLASS		40.044910,-102.328560

Comment:	Fiberglass water tank 50% buried next to meter shed	
Corrective Action:		Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 253225 Type: WELL API Number: 125-07102 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT