

Inspection Photos

Loc#335553

Operator: Ursa

Inspection Number: 692402014

Inspection Date: 3/17/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location from entry.

March 17, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Ursa Valley Farms I Pad Loc#335553



Photo#2:
Stormwater issue Northwest pad berm.



Photo#3:
Stormwater issue at East side berm.

March 17, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Ursa Valley Farms I Pad Loc#335553




Photo#4:
Wildlife Escape Boards in Well cellars are not in position to allow means of Wildlife egress.

March 17, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#5:
Wildlife Escape Boards in Well cellars are not in position to allow means of Wildlife egress.

Inspection Photos: Ursa Valley Farms I Pad Loc#335553