

Inspection Photos

Location Name: Ehler 44-4 Location ID: 320460, Remediation Project 12779



Photo 1 – Location Sign Posted



Photo 2 – Overview of site from entrance

Inspection Photos

Location Name: Ehler 44-4 Location ID: 320460, Remediation Project 12779



Photo 3 – Overview of site from west side, looking southeast.



Photo 4 – Overview of site from west side looking east.

Inspection Photos

Location Name: Ehler 44-4 Location ID: 320460, Remediation Project 12779



Photo 5 – Damaged monitoring well within fenced area.



Photo 6 – Overview of south end, looking northwest.



Inspection Photos

Location Name: Ehler 44-4 Location ID: 320460, Remediation Project 12779



Photo 7 – Monitoring wells near northeast corner of site.



Photo 8 – North perimeter of site looking west.

Inspection Photos

Location Name: Ehler 44-4 Location ID: 320460, Remediation Project 12779



Photo 9 – Drainage swale through center of site, looking south-southwest.



Photo 10 – Drainage swale through center of site, looking north.

Inspection Photos

Location Name: Ehler 44-4 Location ID: 320460, Remediation Project 12779



Photo 11 – Monitoring well north of site perimeter.



Photo 12 – Monitoring wells north of site perimeter.



Inspection Photos

Location Name: Ehler 44-4 Location ID: 320460, Remediation Project 12779



Photo 13 – From south end of site looking north along eastern perimeter.

