

Inspection Photos
Location Name: Baggs Land and Cattle 1
Location ID: 312868



Photo 1. Overview of location taken facing northeast.

Inspection Photos
Location Name: Baggs Land and Cattle 1
Location ID: 312868



Photo 2. Gauge hatch open on tank.



Photo 3. Example of erosion gully forming on location.