

FORM
INSPRev
X/15State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/27/2020

Submitted Date:

03/27/2020

Document Number:

700700369

FIELD INSPECTION FORM

 Loc ID 335514 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____
Operator Information:

OGCC Operator Number: 10531

Name of Operator: GRIZZLY OPERATING LLC

Address: 5847 SAN FELIPE #3000

City: HOUSTON State: TX Zip: 77057

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

13 Number of Comments

0 Number of Corrective Actions

 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
, Grizzly		sghan@grizzlyenergyllc.com	SR. EH&S
, Grizzly		aaxelson@grizzlyenergyllc.com	
, Grizzly		scollett@grizzlyenergyllc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
299032	WELL	PR	07/16/2009	GW	045-17544	JOLLEY 31A-21-691	PR
299033	WELL	PR	08/27/2009	GW	045-17545	JOLLEY 31B-21-691	PR
299034	WELL	PR	07/13/2009	GW	045-17546	JOLLEY 31C-21-691	PR
299035	WELL	PR	07/31/2009	GW	045-17547	JOLLEY 31D-21-691	PR
299071	WELL	PR	10/23/2009	GW	045-17551	GGU JOLLEY FEDERAL 21D-21-691	PR
299076	WELL	PR	07/20/2009	GW	045-17552	JOLLEY 21A-21-691	PR
299077	WELL	PR	08/01/2019	GW	045-17553	JOLLEY 21B-21-691	PR
299078	WELL	PR	09/03/2009	GW	045-17554	JOLLEY 21C-21-691	PR

General Comment:**COGCC Inspection Report Summary**

On Friday 3/27/20 at approximately 10:30 AM, I, Inspector Scott Ramsey, conducted a routine inspection at Grizzly Jolley 4, at Location # 335514 in Garfield Colorado.

While there, I observed normal production operations. Roustabouts were on location pulling out dead men. There is also an air compressor on location that the roustabouts are using for cleaning of equipment.

This is a summary of inspection report.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	DEBRIS		
Comment:			
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Equipment:			
Type: Emission Control Device	# 1		corrective date
Comment:			

Corrective Action:		Date:	
Type: Plunger Lift	# 8		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 8		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 15		
Comment:	these are being removed while on location		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 8		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	5	500 BBLs	HEATED STEEL AST		,
Comment:	two tanks are not heated				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type	Ignitor/Combustor		
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	299032	Type:	WELL	API Number:	045-17544	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	299033	Type:	WELL	API Number:	045-17545	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	299034	Type:	WELL	API Number:	045-17546	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	299035	Type:	WELL	API Number:	045-17547	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	299071	Type:	WELL	API Number:	045-17551	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	299076	Type:	WELL	API Number:	045-17552	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	299077	Type:	WELL	API Number:	045-17553	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	299078	Type:	WELL	API Number:	045-17554	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				

--

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms		Berms				
		Gravel				
		Ditches				
		Check Dams				
Gravel		Culverts				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700700373	photos for Jolley 4	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5107287