

Terra Rocky Mountain LLC GL_Valley / CS_Starkey Facility ID # 464247



Terra Rocky Mountain LLC
GL_Valley / CS_Starkey
Facility ID # 464247



Stained soil at exhaust.



Stained soil between flow lines and compressor shed.

Terra Rocky Mountain LLC
GL_Valley / CS_Starkey
Facility ID # 464247



5 gallon bucket stored out secondary containment.

Terra Rocky Mountain LLC
GL_Valley / CS_Starkey
Facility ID # 464247



Tank missing Operator Name, Contact number, and Capacity.