



WELL SITE INSPECTION FORM

WELL NAME Allis 1-10 API NUMBER 05 - 001 - 08458
OPERATOR Gusher O & E PERMIT NUMBER 86-671
LOCATION SWSW 10-25-60W COUNTY Adams
FIELD Buckskin INSPECTOR Brinkley

AL/PA/DA INSPECTION RESULTS: WELL STATUS:
PASS (Y) FAIL (N) DATE 5-7-90 FN FD WO

DATE OF INSPECTION BEFORE/DURING DRILLING

CASING SIZE DEPTH SET CMT VOL WOC
CONSISTENT WITH APD CASING PROGRAM? RETURNS
RIG BOP'S CONTACT

DATE OF INSPECTION BEFORE/DURING/AFTER COMPLETION

PIPE SET? COMPLETION RIG/ACTIVITY
DRILLING PITS: CLOSED OPEN WELLHEAD SYSTEM INSTALLED
TANK ID: YES NO NA WELL SIGN: YES NO
SKIM PIT: gal TANKS: () bbls
EQUIPMENT
BRADENHEAD PRESSURE FLUID: NO YES TYPE
METER RUN: YES NO WELL STATUS: PR TA SI WELL CAT 3-

AL/PA/DA INSPECTION

DATE PLUGGED: DATE PERMIT EXPIRED:
HOLE PLUGGED: YES NO PITS BACKFILLED: YES NO
MATERIAL BURIED: YES NO NA SITE CLEAN: YES NO
BOND RELEASE OK: YES NO FED HOLE MARKER: YES NO

DATE OF SAFETY/STATUS INSPECTION

COMMENTS casing not out of below ground line
Location over ground where - Complaint by Farmer

5/15/90 - ED - Don't see where/how we can do ANYTHING NOW. IT
IS EMBARRASSING TO FIND OUT ^{my} ERRORS. I'm SURE you'll get THIS
pleasure SOMEDAY TOO. I WILL MAKE A COPY OF THIS FOR ENVIRONMENTAL
RESPONSE FUND, AS WE MAY UTILIZE IT TO CORRECT THIS TYPE OF
PROBLEM SOMEDAY.

JSK