

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/30/2020

Submitted Date:

03/30/2020

Document Number:

701000362**FIELD INSPECTION FORM**Loc ID 337732 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10699Name of Operator: OWN RESOURCES OPERATING LLCAddress: 38 PALMER CREST CTCity: SPRING State: TX Zip: 77381**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**11 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Jones, Greg	(970) 630-3909	greg.jones@ownresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
288372	WELL	PR	04/16/2007	GW	125-10537	GREENFIELD 15-13	PR

**General Comment:**Routine Inspection

## Location

<b>Lease Road:</b>			
Type	Access		
comment:	Trail through CRP		
Corrective Action	L	Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	Lease signs by meter sheds		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Lease sign by unit		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Pump Jack	# 1		
Comment:	Jensen unit		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Kubota gas engine		
Corrective Action:		Date:	
Type: Vertical Separator	# 2		
Comment:	2-Vertical gas separators 50% buried by meter sheds		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Gas scrubber and telemetry equipment at meter sheds		
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:	Shared meter run for Greenfield 15-13 and Kiser 15-10 1080' WSW of wellhead		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		

Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	288372	Type:	WELL	API Number:	125-10537	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing. Casing production. Central meter run for (Greenfield 15-13 and Kiser 15-10) 1080' WSW on north side of CR 27								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Other	Pass			

Comment: 

Access is grassed over

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT