

Inspection Photos
Location Name: Rohn State LD10-65HN
Location ID: 433197



Photo 1 – Tank Battery



Photo 2 – East Wells

Inspection Photos
Location Name: Rohn State LD10-65HN
Location ID: 433197



Photo 3 – East Well Signage



Photo 4 – Eastside Chemical tank – missing/faded Label

Inspection Photos
Location Name: Rohn State LD10-65HN
Location ID: 433197




Photo 5 – Eastside Chemical tank – missing/faded Label




Photo 6 – Eastside Chemical tank – missing/faded Label

Inspection Photos
Location Name: Rohn State LD10-65HN
Location ID: 433197



Photo 7 – West Wells



Photo 8 – Westside Signage



Inspection Photos
Location Name: Rohn State LD10-65HN
Location ID: 433197



Photo 9 – Westside Chemical tank – missing/faded Label



Photo 10 – Produced Water Tanks missing Signage

Inspection Photos
Location Name: Rohn State LD10-65HN
Location ID: 433197



Photo 11 – Compressor Drain tank – missing Signage and Stained Soil