

# Inspection Photos

3/30/2020

Operator: RIO MESA RESOURCES INC - 74740

Location ID: 315237

Rio Blanco County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

## Inspection Photos

Operator Name: RIO MESA RESOURCES INC - 74740

Location ID: 315237



**Photo 1:** Photo taken from the east end of the Location, facing south. Photos 1-4 provide an overview of the Location from south, southwest, northwest to north. Location appears to have been PA in 2018. Photo shows equipment remaining on the Location and no reclamation activities appear to have been conducted in accordance with COGCC 1004 rules.

**Photo 2:** See comments under photo 1.

Inspection Photos  
Operator Name: RIO MESA RESOURCES INC - 74740  
Location ID: 315237



**Photo 3:** See comments under photo 1.



**Photo 4:** See comments under photo 1.

Inspection Photos  
Operator Name: RIO MESA RESOURCES INC - 74740  
Location ID: 315237



**Photo 5:** Photo taken from the well site, facing northwest. Photo shows well appears to have been plugged; Pumping unit remains on the Location.



**Photo 6:** Photo taken from the well site, facing south. Photo shows well appears to have been plugged; Pumping unit remains on the Location.

## Inspection Photos

Operator Name: RIO MESA RESOURCES INC - 74740

Location ID: 315237



**Photo 7:** Photo shows unused equipment remaining on the north end of the Location.



**Photo 8:** Photo taken from the west end of the Location, facing south. Photo shows a pit remains open on the Location.

## Inspection Photos

Operator Name: RIO MESA RESOURCES INC - 74740

Location ID: 315237



**Photo 9:** Photo taken from the southwest end of the Location. Photo shows equipment remaining (Vertical Heater Treater, Utility pole) on the Location.



**Photo 10:** Continued from photo 9. Photo shows stained soils due to leaks from unused equipment.

Inspection Photos  
Operator Name: RIO MESA RESOURCES INC - 74740  
Location ID: 315237



**Photo 11:** Continued from photo 9.



**Photo 12:** Photo taken from the southeast end of the Location, facing south. Photo shows unused equipment (two 400bbl AST) remaining on the Location.

Inspection Photos  
Operator Name: RIO MESA RESOURCES INC - 74740  
Location ID: 315237



**Photo 13:** Photo shows stained soils due to leak from tanks.



**Photo 14:** Photo shows stained soils observed on the southeast end of the Location, south of the tanks.