

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

03/26/2020

Submitted Date:

03/26/2020

Document Number:

697000908

**FIELD INSPECTION FORM**
 Loc ID 330583 Inspector Name: Peterson, Tom On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL &amp; GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

4 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspections@anadarko.com	
,		dnr_cogccengineering@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
Kraich, Adam		adam.kraich@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
251511	WELL	SI	10/01/2019	GW	123-19314	HSR-SPAUR 7-7	TA

**General Comment:**

**Location**Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:		
Corrective Action:		Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

**Equipment:**

Type: Bradenhead	# 1		corrective date
Comment:	Bradenhead valve is exposed at surface.		
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:	Tank battery #425986				
Corrective Action:				Date:	

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance



**Inspected Facilities**Facility ID: 251511 Type: WELL API Number: 123-19314 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Well was found in state of Temporary Abandonment. See attached photos.  
Well is overdue for Mechanical Integrity Test (MIT). MIT require 10 day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to plug well.

Corrective Action: Perform successful mechanical integrity test. If a successful MIT can not be performed within 30 day CA time the well must be plugged within 3 months per Rule 326 and 208.

Date: 04/28/2020**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402353477	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5106058">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5106058</a>
697000909	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5106056">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5106056</a>