

Ant Hill Unit 28-44  
API: 05-103-10221  
Inspection: 700400812



40.11165, -108.17636, 5827.2ft, 201°  
04/01/2020 03:34:04 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 1. Location.**

Ant Hill Unit 28-44  
API: 05-103-10221  
Inspection: 700400812



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 2. Well head, tanks, and storage building.**



Ant Hill Unit 28-44  
API: 05-103-10221  
Inspection: 700400812



40.10773, -108.16442, 5875.0ft, 355°  
04/01/2020 03:25:34 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Photo 3. Tanks.

Ant Hill Unit 28-44  
API: 05-103-10221  
Inspection: 700400812





Ant Hill Unit 28-44  
API: 05-103-10221  
Inspection: 700400812



40.10733, -108.16456, 5866.4ft, 219°  
04/01/2020 03:24:43 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 5. Unmarked deadman in SW corner of pad.**