

Inspection Photos

Loc#311545

Operator: Terra

Inspection #: 692402031

Inspection Date: 3/24/20





Photo#1:
Overview of Location to Northwest and fill slope vegetation.

March 24, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra DOE Loc#311545



Photo#2:
Washout on access road.

Photo#3:
Washout on access road.

March 24, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra DOE Loc#311545



Photo#4
Stormwater concern on cut slope.



Photo#5:
Stormwater concern on fill slope.

March 24, 2020