



Form Information

| | |
|----------------------|--|
| Form Name: | Compliance Follow Up Form |
| Submitter Name: | Cole Nichols (colen@horizonenvservices.com) |
| Submission Date: | Apr 1, 2020 10:03:14 AM MDT |
| Server Receive Date: | Apr 1, 2020 10:06:16 AM MDT |
| Reference Number: | 20200401-18138130152 |
| Location: | 557 Airpark Dr, Durango, CO 81303, USA Apr 1, 2020 10:03:01 AM MDT [View Map] |

Information

| | |
|-----------------|------------------------------|
| Name | colen@horizonenvservices.com |
| Date | Mar 30, 2020 |
| Well Name | WIRT GAS UNIT D DK 2M |
| API Number | 50670634000 |
| Select State | Colorado |
| Work type | COGCC Inspection AR |
| Action Complete | Clean Up Weed Debris |

Photo of first corrective action completed



Completed work description Corrective Action 1

location sign

Photo of second corrective action completed



Completed work description of corrective action 2

removed weed debris from location

Photo of third corrective action completed



Completed work description of corrective action 3
Photo of fourth corrective action completed

removed weed debris from location



Completed work description
Completed work description of corrective action 4
Completed work description
Summary of all work completed

removed weed debris from location
removed weed debris
removed weed debris
previous treatment dates 7/19/16, 3/30/17, 6/11/18,
marked as p&a 2019